



## Needed Tools


PH2; 3x0,5; Cable cutters; TX10; TX25




I TX25



II



III TX10



IV

