


Needed Tools


PH2; 3x0,5; Cable cutters; TX10; TX30; Drill;





I




PH2




3x0,5




PH2




II TX30



III



IV TX10



V

