



Needed Tools


PH2; 3x0,5; Cable cutters; TX10; TX30




I TX30



II



III TX10



IV

