


Needed Tools


PH2; 3x0,5; Cable cutters; TX6; TX10; Drill; HEX 0,5




I 0,5




II




III + PH2




IV + PH2




V - 3x0,5




VI




VII + PH2




VIII



IX



X TX6-MINI1;TX10-MIDI,MAXI



XI

