



Needed Tools


PH2; 3x0,5; Cable cutters; TX6




I TX6



II



III TX6



IV

