


Needed Tools

PH2; PZ1; Cable cutters; HEX 1,5




1,5


I 1,5




II




III




IV PZ1




V




VI




VII




VIII



IX



X



XI

