


Needed Tools

PH2; TX10; Cable cutters; HEX 1,5




1,5



I 1,5





II





III




IV TX10




V




VI




VII




VIII



IX



X



XI

