


Needed Tools

PH2; 3x0,5 Cable cutters, 7




I



II



3x0,5



III



7

