


Needed Tools


PH2; 3x0,5; Cable cutters; 7




I PH2




II PH2 3x0,5





III 7




IV



V



VI 3x0,5



VII

