


Needed Tools


PH2; 3x0,5; Cable cutters; 7




I PH2




II PH2 3x0,5



III 7



IV



V 3x0,5

