


Needed Tools


PH2; 3x0,5; Cable cutters; 7




I PH2




II 3x0,5



IV



III 7



V 3x0,5

