


Needed Tools


PH2; 3x0,5; Cable cutters; 7




I




II 3x0,5



IV



III PH2



V 3x0,5

