



Needed Tools


PH1; PH2; Cable cutters; 8; TX20; HEX 5




I TX20




II




III PH1




IV




V PH1



VI 8



VII



VIII 5



IX PH1

