


Needed Tools



PH1; PH2; Cable cutters; TX20; HEX 5




I TX20




II




IV PH1




V




VI 5



VIII



IX PH2



VII PH1

