


Needed Tools


PH2; 3x0,5; Cable cutters; 7; HEX 3




I 3




II




III PH2



IV



V 7



VI 3x0,5

