


Needed Tools


PH2; 3x0,5; Cable cutters; HEX 2,5; HEX 3




I




II PH2





III



IV 3x0,5



V



VI 2,5

