


Needed Tools


PH2; 3x0,5; Cable cutters; TX10





I TX10




II



III 3x0,5



IV



V PH2

