


## Needed Tools


PH2; 3x0,5; Cable cutters; TX10




I TX10




II




III 3x0,5




IV




V



VI 3x0,5



VII



VIII PH2

