


Needed Tools


PH2; 3x0,5; Cable cutters; TX10




I ★ TX10




II




III




IV




V + PH2



VI



VII



VIII — 3x0,5

