


Needed Tools


PH2; 3x0,5; Cable cutters; TX10




I TX10




II TX10




III



IV



V 3x0,5



VI

