


Needed Tools


PH2; Cable cutters; HEX 3; 3x0,5




I 3




II PH2




III




IV PH2



V 3x0,5



VI



VII PH2

