




Needed Tools


PH2; Cable cutters; 3x0,5; TX10




I 3x0,5




VI




V TX10



VI



VII



VIII  PH2