


Needed Tools


PH2; 3x0,5; Cable cutters; Hammer




I  3x0,5





II 




III  PH2




IV 





V



VI 



VII  3x0,5



VIII

