



Needed Tools


PH1; PH2; Cable cutters; 8; 19; TX10; TX20




I ★ TX20




II




III + PH1




IV




V + PH1




VI 8





VII



VIII 19



IX  TX10X XI  PH2