


Needed Tools


PH2; Cable cutters; TX10; Drill




I



II PH2



III



IV TX10

