


Needed Tools


PH2; Cable cutters; 3x0,5; Pliers




I 3x0,5





II 3x0,5




III




IV




V PH2



VI



VII



VIII

