


Needed Tools


PH2; Cable cutters; 3x0,5;




I  3x0,5





II  3x0,5




III




IV 




V  PH2




VI



VII



VIII 



IX  3x0,5

