


Needed Tools


PH2; Cable cutters; 3x0,5




I  3x0,5





II  3x0,5




III




IV 




V  PH2




VI




VII  3x0,5



VIII



IX 



X

— 3x0,5

