


Needed Tools


PH2; Cable cutters; 3x0,5; Pliers




I 3x0,5





II 3x0,5




III




IV





V PH2




VI




VII 3x0,5



VIII



IX



X

