

DL60 Driver and LED disassembly

Needed tools


T10; Flat; Crosshead #1; Hammer




Recycle waste




Driver disassembly




COB LED disassembly



7



8



9

