



Needed Tools


PH2; 6x1; 3x0,5; Cable cutters




VII 



VIII



IX 



X  PH2

