


Needed Tools

PH2; Cable cutters; TX10




I TX10




II




III




IV PH2




V



VI PH2





VII



VIII



IX



X

