


Needed Tools


PH2; 3x0,5; Cable cutters




I PH2




II




III 3x0,5




IV PH2




V



VI PH2



VII



VIII 3x0,5

