


# Needed Tools


PH2; 3x0,5; Cable cutters; 7




I PH2




II




III




IV 7



V PH2



VI



VII 3x0,5

