


## Needed Tools


PH2; Cable cutters; HEX 4




I




II




III




IV



V



VIA



VIB

