


Needed Tools


6x1,2; 3x0,5; Cable cutters; 8




I 6x1,2



II



III 8



IV 3x0,5

