


## Needed Tools


PH2; Cable cutters; HEX 3




I 3




II




III




IV




V



VI



VII + PH2



VIII

