




[1] PRODUCT QUALITY ASSURANCE NOTIFICATION

[2] Equipment or Protected System Intended for use
in Potentially explosive atmospheres
Directive 2014/34/EU

- [3] Notification Number: Nemko 03ATEX089Q
- [4] Equipment or Protective System or Components as listed: Fluorescent Luminaries; LED Luminaries; Recessed Indoor Luminaires; Recessed Indoor LED Luminaires; Lamp Holders; Terminal Blocks; Battery boxes
 II 2/3 G/D Ex d; Ex e; Ex m; Ex nA; Ex t, Ex op is
- [5] Applicant – Manufacturer or Authorized representative in the Community: Glamox AS
Birger Hatlebakks veg 15
6405 Molde
NORWAY

[6] Nemko AS, notified body number 0470 for Annex IV/VII in accordance with Article 17 of Council Directive 2014/34/EU of 26 February 2014 notifies to the applicant that the actual manufacturer has a product quality system which complies with Annex VII of the Directive.

[7] This notification is based on audit report issued the 2018-04-27, related to order No. 349998, as well as corresponding corrective actions.
Information about external factory site(s) covered by this QAN - if any - is given in audit reports related to the validity of this QAN.


The notification can be withdrawn if the manufacturer no longer satisfies the requirements of Annex VII.
Results of periodical surveillance of the quality system are a part of this notification.

[8] This notification is valid until 2021-07-31 and can be withdrawn if the Manufacturer does not satisfy the product quality assurance surveillance / re-assessment.

[9] According to Article 16(3) of the Directive 2014/34/EU the CE marking shall be followed by the identification Number 0470, identifying the notified body involved in the production control stage.

This notification may only be reproduced in its entirety and without any change, schedule included – if any.

2018-07-06



Bernt Jonny Orderud
Manager factory inspections
Factory Inspection Department