


## [1] PRODUCT QUALITY ASSURANCE NOTIFICATION

[2] Equipment or Protected System Intended for use  
in Potentially explosive atmospheres.  
Directive 2014/34/EU

- [3] Notification Number: Nemko 03ATEX089Q
- [4] Equipment or Protective System or Components as listed: Fluorescent Luminaries; LED Luminaries; Recessed Indoor Luminaires; Recessed Indoor LED Luminaires; Lamp Holders; Terminal blocks; Battery boxes.  
 II 2/3 G/D Ex d; Ex e; Ex m, Ex op is; Ex t; Ex nA
- [5] Applicant – Manufacturer or Authorized representative in the Community: Glamox AS  
Birger Hatlebakks veg 15  
6415 Molde  
NORWAY
- [6] Nemko AS, notified body number 0470 for Annex IV/VII in accordance with Article 17 of Council Directive 2014/34/EU of 26 February 2014 notifies to the applicant that the manufacturer has a production quality system which complies with Annex VII of the Directive.
- [7] This notification is based on audit report issued the 2021-04-14, related to order No. 419811, as well as corresponding corrective actions, if any.  
Information about external factory site(s) covered by this QAN - if any - is given in audit reports related to the validity of this QAN.
- The notification can be withdrawn if the manufacturer no longer satisfies the requirements of Annex VII.  
Results of periodical surveillance of the quality system are a part of this notification.
- [8] This notification is valid until 2024-07-31 and can be withdrawn if the Manufacturer does not satisfy the product quality assurance surveillance / re-assessment.
- [9] According to Article 16(3) of the Directive 2014/34/EU the CE marking shall be followed by the identification Number 0470, identifying the notified body involved in the production control stage.

*This notification may only be reproduced in its entirety and without any change, schedule included – if any.*

2021-04-27



**Bernt Jonny Orderud**  
Manager factory inspections  
Factory Inspection Department